VIN Decoded

2022 Volkswagen Golf GTI

Hatchback · Front-Wheel Drive · Manual/Standard · Petrol · Gas Guzzler

Vehicle Overview

Year 2022	Drive Type FWD
Engine 2.0L L4 Tur	Fuel Type Gasoline
Transmission 6 Speed DSG	Seats 5
Doors 4	Body Hatchback

Quick Specifications

Turbocharged	Gas Guzzler	Manual/Standard	Front-Wheel Drive
4 Cylinder	2.0 Liter	Gasoline	Compact Cars
MPG Regular	Fuel Economy	Hatchback/Liftback	Volkswagen

Mileage History

Date	Mileage	Source
Dealer Service 04/08/2022	45,220 km	
Owner Check 05/05/2023	55,000 km	DISCREPANCY
MOT Inspection 04/04/2024	58,000 km	
Dealer Service 05/05/2025	59,127 km	
Insurance Inspection 05/05/2025	59,417 km	
MOT Inspection 04/04/2026	59,988 km	
Dealer Service 05/05/2026	6,720 km	
Insurance Inspection 05/05/2026	7,000 km	

Mileage Trend

Accident History

Accident Found
Accident Count: 1

Damage: Rear end collision in parking lot

Estimate: $ 32,800 Repair Cost

Aug 14, 2020

Damage: Rear End

Severity: Disabling

Airbags: Deployed

Drivable: Yes

Front-end damaged

Total Loss Threshold: $ 27,500

Total Loss Threshold based on Kelley Blue Book Fair Purchase Price. Actual threshold varies by state.

MOT / Inspection History

Vehicle Passed
December 7, 2025

Date	Result	Odometer
December 6, 2024	PASSED (1 Minor Defect)	
Advisories: Front brake pads worn (Minor)		
December 12, 2023	PASSED	41,200 mi
Tyre condition (Minor)		
December 10, 2022	PASSED	38,500 mi
Brake pipes - corrosion, leak, damage, pipes worn (Minor)		
Suspension - excessive play detected (Minor)		
Pre-production inspection and vehicle health check		
Brake hoses - chafing, damage, perished, cracking (Minor)		
Manual service - oil change, air filter, cabin filter		
Brake fluid - moisture content high (Minor)		
Rear suspension bushings replacement		
December 11, 2021	PASSED	32,000 mi
Manual service and pre-delivery inspection		
Front brake pads and discs replacement		
Front suspension bushings replacement		
Rear suspension - bushings, shock absorbers, springs		
Pre-production inspection and vehicle health check		
Manual service - oil change, air filter, cabin filter		
Brake fluid - moisture content high (Minor)		
Rear suspension bushings replacement		
Brake hoses - chafing, damage, perished, cracking (Minor)	

August 15

Minor accident - rear collision

July 20

Recall 23V-456 completed

July 14

Service completed - 24,300 miles

June 15

Recall 23V-456 issued

2022

December 15

Recall 22V-892 completed

December 10

MOT Passed - 12,850 miles

November 3

Recall 22V-892 issued

June 20

First service completed

March 15

Sold at dealership - $38,900

March 15

First Registration